

Change Notification

March 21, 2017

Dear Valued Client,

It has recently been brought to our attention that one of our vendors who supplies Tyvek® and Tyvek®/Mylar® pouches utilized as the primary packaging for some of the product configurations sold by Crosstex International, Inc., has changed the location of their manufacturing operations. The following Product Codes are packaged in the materials which are supplied from this vendor:


Product Codes Primarily Packaged in Tyvek or Tyvek/Mylar Pouches:

Organism	Packaging Type	Product Codes
<i>Geobacillus stearothermophilus</i>	Tyvek	TTS-03, TTS-04, TTS-05, TTS-06, TCDS-06
<i>Bacillus atrophaeus</i>	Tyvek	TTN-03, TTN-04, TTN-05, TTN-06
<i>Geobacillus stearothermophilus</i>	Tyvek/Mylar	CPS-04, CPS-05, CPS-06, GFTS-04, GFTS-05, GFTS-06, SDS-04, SDS-06
<i>Bacillus atrophaeus</i>	Tyvek/Mylar	CPN-04, CPN-05, CPN-06, GFTN-04, GFTN-05, GFTN-06, SDN-06

The vendor has provided a thorough validation associated with the change. The validation has been reviewed and it has been determined that there is no impact associated with the change in regards to the products Crosstex International, Inc., provides to our clients. This determination was based upon the scope of the change relating to the physical location of the vendor's operations. There has been no change to their quality system, equipment, materials, staff/personnel, manufacturing process, sampling or testing.

If you would like a copy of the validation performed by the vendor, please contact Customer Service at productorders@crosstex.com.

Best regards,



Julie Wheeler
Director, Industrial Markets
jwheeler@crosstex.com
567-803-1207